

Photo Documentation Log	
Photo Number	Description (include date, location and direction)
1	Tank 3 - high water line along steel of tank and water around foundation
2	Tank 7 - vegetation growing between foundation and chime
3	Groundhog hole in secondary containment
4	South side dike of Revco Facility has slumped over a product pipe and the pipe is half buried & pipe supports have failed
5	
6	
7	
8	
9	
10	
11	